

DEPARTMENT OF TRANSPORTATION**DIVISION OF ENGINEERING SERVICES**

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch

690 Walnut Ave.St. 150

Vallejo, CA 94592-1133

(707) 649-5453

(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 99.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-025949**Date Inspected:** 31-Jul-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC) Chanxing Island**Location:** Shanghai, China**CWI Name:** N / A**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Segment**Summary of Items Observed:**

On this date CALTRANS OSM Quality Assurance (QA) Inspector Santhosh Ramakrishna Pillai was present during the times noted above for observations relative to fabrication work of the Self Anchored Suspension (SAS) Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China.

This QA inspector randomly observed the following work:

1. NDT:

Segment Tagging

Magnetic Particle Testing (MT):

MT carried out for the ZPMC submitted Notification for Witness.

This QA Inspector randomly performed & witness Magnetic Particle Testing (MT) of approximately 15% of the area that has been previously tested and accepted by ZPMC MT technicians. This QA Inspector generated a TL-6028 MT report on this date. The members are identified as fillet & CJP weld joint located on 13BE. The weld designation numbers is as follows:

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

1. SEG3009G-155
2. SEG3009G-191
3. SEG3009J-314
4. SEG3009J-315
5. SEG3009J-316.

MT carried out for the ZPMC submitted Notification No 09845.

This QA Inspector performed Magnetic Particle Testing (MT) of approximately 15% of the area that has been previously tested and accepted by ZPMC MT technicians. This QA Inspector generated a TL-6028 MT report on this date. The members are identified as fillet & CJP weld joint located on 13BE. The weld designation numbers is as follows:

1. SEG3009B-024
2. SEG3009G-273,
3. SEG3009G-293,
4. SEG3009G-299,
5. SEG3009G-307.

Ultrasonic Testing (UT):

UT carried out for the ZPMC submitted Notification No 09845.

This QA Inspector performed Ultrasonic Testing (UT) on approximately 10 % of CJP welds that has been previously tested and accepted by ZPMC ultrasonic technicians in accordance with AWS D1.5-2002, section 6, table 6.3. The members are identified as CJP weld joint located on 13BE. This QA inspector generated a UT (TL-6027) report for this date. Weld identification numbers were

1. SEG3009F-090,118.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No relevant conversations were reported on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 150-0042-2372, who represents the Office of Structural Materials for your project.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Inspected By: Pillai,Santosh

Quality Assurance Inspector

Reviewed By: Miller,Mark

QA Reviewer